

Amendments to the Specification:

Please replace the paragraph beginning on page 3, line 18, with the following rewritten paragraph:

Such a possibility does not exist in document WO 01/8552601/855263, in which the stiff frame is directly mounted on the rear bearing runner, to which it is rigidly attached. Also, the fork of the steering column is directly attached to the directional runner. Only the tilted stabilization bar of the stiff frame is interrupted by an impact-absorbing elastic device, which works in association with a supporting sole separated into two sections with approximately equal length.